ENGINEERING CHANGE NOTICE DART AEROSPACE LTD

								1.1/21	
Date:	08.01.25	Job No.:	00241	ADR Yes/No:	/ Y	ADR Date:	08.01.21	EEN#:	1128
Product No.:	D206-746			Created By:	PH	Approved By:		5en #.	1120
Product Name:	SHROUD AIRFLOV	VHEATER		Checked By:	خد	General Mana	ger Approval		

Distribution	Reqd	Resp	Received	Distribution	Reqd	Resp	Received
Production Manager	Х	LL	/	Customer Technical Support	Х	DStow	
Production Engineering Coord X		DD/EC		Marketing	1		
Director Quality Assurance							
Customer Order Processing							

Reason for Change: Bearings on Janitrol Moto	or are failing prematurely		
Documents Affected:			
D3742 Rev B	(see below)		

	Engineering Actions	Reqd	Resp	Notes	Complete
1	Required Documents/Drawings Under Review	Υ	PH		03.04.11 124
2	Update Blue/Pink/DSI Folder and Electronic Files	N			
3	Update D-Part/M-Drawing/DSI/DEO Master Binders	Υ	KJ		08.02.11.9
4	Update Grey Project Binder	Υ	KJ		08.02.11
	Move Electronic Files	—Y—	— кл		08,02,11 95
6	Update Master Document List (MDL) Rev. G	Υ	PH		08.02.11
7	Update Document Record (DR) Rev. E	Υ	KJ		08.02.11
8	Create/Update Change Record Form	N			
9	Create/Update PPP's	N			
10	Update Controlled PDF Files	Υ	KJ		08.02.1194
	Notify TC/FAA of Change	N			100000
12	Update QSI 021 and/or STC Approval List	N	-		
13	Update Product Development Summary	N			
14	Update Accpac Database	N			
	Update Access (ARC) Database	N			
16	Update/Verify ARC	N			
17	Update Paperwork Kits in Production	Y	KJ	For kits equipped with new bearing only	More in Prod 154-08.00
18	Update Qpulse/Laminated Dwgs	N			
19	Update Product Compatability Matrix	N			4
20	Create Eurocopter Form (FEE)	N			
21					

#	Production Actions	Reqd	Resp	Notes		Complete
22	Create/Update Coss IPP/BOM	Y	EC/DD		`	
23	Update FAI Sheets	N				
24	Create/Update CNC Programs	N				
25	Create/Update Tooling	N				
26	Red Tag Stock (Specify)	N				- T
27	Rework/Scrap Current Production and/or Stock	Υ	LL	Change bearing on 26D71 motor	11/2	2000-11
28	Update Paperwork Kits in Stock	Y	KL	For kits equipped with new bearing only	MO	373950
29	Create/Update MPP	N				
30						

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
31	Notify Previous Customers	Υ	DStow		
32	Notify Eurocopter France	N			
33					

I	Description / Action: D3742 Rev B (McMaster D6661K82 bearing) will replace D3742 Rev A bearing If 26D71 Motors were re-worked per ECN #1117, these MUST be reworked as well.	D206-746-011 (1 INSTOCK, OIN PROD) D3742-1 (8 IN STOCK)
L	ALL DS742 REVA BEARINGS NEED TO BE OLVARANTINE	D CHANGED BACK TO VENDORS P/N 2507-13

ECN Verified & Complete:	Date:	